

Dolantidelivery

23.03.2017

Numbe

Marri

369

Supplier "NNK-Bunker"

Физический поетильну ООО "14НК-Бунж 55, Fontainaya str. of the 301, Yladivostok, Ruis tel/fax: •7 (42) (42) (4 2) (5 b-hait office@arks) ake in

BUNKER DELIVERY NOTE

жина поставку бункерного жилива:

Name of vesse

CMA CGM ALMAVIVA

Новерние сужно

IMO Number of receiving vassal ИМО принимающего судна

Borge Бункеровилки

ZALIV NAKHODKA

Part of delivery

NAKHODKA

- AND 1931 CONT. - 1940 CO.

Product/Grade

«тери**сти**ку нефтепродукта:

- 31.840 Bi

PRODUCT/GRADE

Топливо судовое остаточное экологическое

Ремуменовиние зувенью

50

The Albanda Maria Control

10.352

-MKRYXXX HO

VISCOSITY of ванакасть през

(anothic tons)

1 900.00

QUANTITY Ковичество

100 1150 BALL 15 °C (kg/m³)

834.9

Пиотносуу FLASH POINT

∛емперогурд‱≋аншки

DENSITY of

. (2000). S [degr.°C]

+167

SULPHUR.

Содержонно серы

(maSS, %)

0.051

WATER SEE

(v/v pel) Содержадууде воды

0.2

Start pumping (date/time):

Наково бункаружа (дого, арема)

23.03.2017 / 18:15

Finish pumping (data/lime):

Company Company (1979) 23.03.2017 / 23:40

Nº пламы пробы бустровины:

Bunker barge samples sed N 0073013,0073014, V541076

Yessel's samples seal No. 0073012, V541074, V541077 № явомби приби **суд**на

essel's MARPOL samples seal N

№ плочебы пробы судно МАРПОЛ:

0073011,V541075

OJE

 G_{Λ}

Thereby certify that the due quantities of declared petroleum products have been recieved by me and filled into engines bunker tanks of the vessel. I am fully aware that the quantity of declared petroleum products are supplied to my vessel as sea stores without payment of customs duty, and shall be used salely by my vessel, l'understand that a breach of this candition is an infringement and I hereby take the responsibility for any violation of this statement.

Настоящим подтверждаю, что мною получено и залито в танки машинного отделения надлежащее количество заявленных нефтепродуктов. Я полностью сахнаю, что полученное топливо принято как судовой принас без уплаты таможенной пошлины и будот использована исключительно для нужд моего судна. Я понимаю, что несоблюдение данного условия рассматривается как нарушение, и настоящим беру на себя ответственность за уклонение от выполнения данного утверждения:

Signature and stamp Captain/Ch. Engineer

Пожиние и изтами Konton/Cr. Mexones

Signature/ch Barge

BELENKO,

The fuel oil is in conformity with rep Token 14(1) or (4) (a) and regulation 18(1) of Annex NXVI MARPOL 73/28. Поставления кидкое пливо скоти ствужите откубите (1) или (4) (а) и провилу 18(1) Приложения № VI (4.4.4.10) год го

Marine fuel oil supplier

Постивыя судового жизкого толиво

LLC «NNK – BUNKER»

бинкоровацика

.*

cwa cgw	LETTER	OF PROTEST	
Market and the second of the s			
From: Chief Engineer		To : The Master and Cargo Officer	
Vessel Name: CMA CGM ALMAVIVA IMO No.: 9450648		Bunker Tanker: TALIV NALLWOK +	
Port Name : NAKHODKA		IMO No.: 8906951	
Location within Port : ANCHORAGE		Supplier's name :	
	A second second		
Grade ordered : RMD 80	Quantity ordered: 1900 MT	Quantity Received: 1900 *MT	
		*MT Subject to laboratory analysis for density and water.	
On behalf of our company and/or charterer(s) we hereby issue this "Letter Of Protest" for the item(s) \square ticked below: (more than one item may be ticked off accordingly)			
 SAMPLING Supplier refused to witness sampling at point of Custody Transfer at the vessel's manifold (not MARPOL compliant). Ship's staff was not invited to witness the taking of commercial samples on board the bunker barge. Supplier refused to counter-seal vessel's samples which were sub-divided from the primary sample. Supplier refused to allow counter-seal of the supplier's samples sub-devided from the primary sample. Supplier refused to record seals/counter-seal numbers on to the BDR. Supplier did not provide a Marpol sample according to MEPC.182 (59) for sampling of fuel oil for determination of compliance with the Annex VI of Marpol 73/78. 			
□ BUNKER QUANTITIES □ The vessel's m tred quantity wasMT but the BDR showedMT was delivered. We are processing that the vessel received onlyMT of fuel ofGrade.			
☐ Ship's staff were not invited to witness barge tanks soundings and temperatures before / after the delivery.			
☐ The vessel received insufficient supply of ordered bunker quantity. The quantity delivered wasMT of(Grade) compared with the Quantity Ordered which wasMT of(Grade)			
 ■ BUNKER QUALITY □ Grade of the fuel stated on the Bunker Requisition Form or Bunker Delivery Receipt was not that ordered by the vessel. □ High Sulfur FO exceeds 3,50%. Non-compliant according to resolution MEPC.181(59) under the Revised Marpol Annex VI. □ ULSFO > 0,10%. Non-compliant according to EU Directive 2012/33/EC □ ULSFO > 0,10%. Non- compliant with the North American ECA requirements & California OGV Fuel Regulation □ MGO Sulfur > 0,10%. Non-compliant with the North American ECA requirements & California OGV Fuel Regulation □ MGO Sulfur > 0,10%. Non-compliant with the North American ECA requirements & California OGV Fuel Regulation 			
☐ CAPUCCINO BUNKERS - EXCESSIVE AIR BLOWING			
There is excessive and prolonged air pumping into the bunker delivery line inspite of our objections. This has resulted in "cappuccino bunkers" with artificially inflated closing soundings. Excessive air pumping as evidenced by the loud cavitation sounds from the cargo pump, fluctuating compound gauge readings and swinging bunker hose was recorded during / / starting at hours and stopping at / / at hours.			
 ☐ OTHERS REASONS ☐ Bunker barge failed to deliver the fuel at the agreed pumping rate. ☐ Bunker barge failed to arrive at the ship at the agreed time and caused a delay of hours. X Other observations: Supplier refused to have following mandatory remark: For volume at temperature observed, final quantity subject to lab tested density' reported on their BDN 			
· · · · · · · · · · · · · · · · · · ·			
PLEASE NOTE :	-		
We reserve the right of recourse to your company at a future date and hold you fully responsible for any direct and consequential damages to the vessel, crew, cargo and environnement that may result from the said defaults in bunkering protocol, processes and incidences noted in the tick box(es) \(\sigma\) above.			
This Protest Note was presented	This Protest Note was presented to the Master/Cargo Officer of the Bunker Tanker.		
	It was □ Accepted and Acknowledged Below or □ Refused		
Instructions to the Master of the Receiving Vessel A crew member or the surveyor (if present) should sign as witness of this document having been presented and accepted or refused by the Supplier. Send a copy to your office for submission to the relevant Port State Control.			
Signed by Master of vessel for and On behalf of Owner / Charterer. Date: 24.35.2017 Time: 52.55		Signed by Bunker Tanker Master/Cargo Officer's Name and Stamped Date:	